

Welding Q&A

11/21/2016

Q1: Clarification on whether a cart will be required for every welder?

A1: No carts will be needed.

Q2: On the photos below, which machine configuration (part number) should be quoted?

A2: XMT 350 #907161 and Dynasty 350 #951 627

350 A	XMT 350 VS (no remote control) (Tweco®) (#907 224) 208-575 V	3-phase	5-425 A 10-38 V	350 A at 34 VDC, 60% duty
	XMT 350 CC/CV (Dinse) (#907 161) 208-575 V			
	(#907 161 011) 208-575 V w/auxiliary power			
	(#951 549) 208-575 V w/SuitCase X-TREME 12VS*			
	(#951 327) 208-575 V MIGRunner w/22A*	1-phase	5-425 A 10-38 V	300 A at 32 VDC, 60% du
	(#951 314) 208-575 V MIGRunner w/S-74D*			
XMT 350 MPa (Dinse except where noted) (#907 366) 208-575 V				
(#907 366 011) 208-575 V w/auxiliary power				
(#907 366 014) 208-575 V w/Tweco®				
Dynasty 350 (#907 204) Machine only	TIG/ stick	3-phase	3-350	
(#951 626) Complete w/foot		1-phase	3-350	
(#951 627) Complete w/wireless foot				

11/22/2016

Clarification on question #2:

Please use the following model numbers as references for complete package welding units as specified in the welding unit bid specifications:

Miller XMT Complete Package 951314 w/out cart. This is the same MIG Welding package we purchased last time but without the cart.