

Welding Q&A

11/21/2016

Q1: Clarification on whether a cart will be required for every welder?

A1: No carts will be needed.

Q2: On the photos below, which machine configuration (part number) should be quoted?

A2: XMT 350 #907161 and Dynasty 350 #951 627

350 A	XMT 350 VS (no remote control) (Tweco®) (#907 224) 208-575 V	3-phase	5-425 A 10-38 V	350 A at 34 VDC, 60% duty
	XMT 350 CC/CV (Dinse) (#907 161) 208-575 V			
	(#907 161 011) 208-575 V w/auxiliary power (#951 549) 208-575 V w/SuitCase X-TREME 12VS*			
	(#951 327) 208-575 V MIGRunner w/22A* (#951 314) 208-575 V MIGRunner w/S-74D*	1-phase	5-425 A 10-38 V	300 A at 32 VDC, 60% du
	XMT 350 MPa (Dinse except where noted) (#907 366) 208-575 V			
	(#907 366 011) 208-575 V w/auxiliary power (#907 366 014) 208-575 V w/Tweco®			

Dynasty 350 (#907 204) Machine only (#951 626) Complete w/foot (#951 627) Complete w/wireless foot	TIG/ stick	3-phase 1-phase	3-350 3-350
---	---------------	------------------------	--------------------